

## ABSTRACT OF THE DISCLOSURE

A method for forming a bump includes the steps of forming a resist layer so that a through-hole formed therein is located  
5 on a pad; and forming a metal layer to be electrically connected to the pad conforming to the shape of the through-hole. The metal layer is formed so as to have a shape in which is formed a region for receiving a soldering or brazing material.